


SICK



DGS35-1L202048

Karolo ea Karolo:

DGS35-1L202048

Moetsi / Mochini:

SICK

Tlhaloso ea Sehlahisoa

ROTARY ENCODR INCREMENT 2048PPR

Datasheets:

Sekepe se Tsoang ho

Hong Kong

Tsela ea Shipment

DHL/Fedex/TNT/UPS/EMS

KOPO EA HO

QOTSA

Setšoantšo e kanna ea ba moemeli. Bona litlhaloso bakeng sa lintlha tsa sehlahisoa.

Litlhaloso tsa DGS35-1L202048













KAROLO EA KAROLO	DGS35-1L202048
MOETSI	SICK
TLHALOSO	ROTARY ENCODR INCREMENT 2048PPR
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	
LEQEPHE LA LINTLHA	
TŠEBELISO EA VOLTAGE	4.5 V ~ 5.5 V
TSELA EA HO KHAOTSA	Cable
SEHLOOHO	-
BOPHELO BA ROTATIONAL (LI-CYCLES MIN)	-
PULSES KA REVOLUTION	2048
TLHAHISO EA MOFUTA	-
MABITSO A MANG	1049681
BOEMO BA BOIKUTLO	User Selectable
MOFUTA OA HO THABA	Chassis Mount
NAKO EA MOETA-PELE E TLOAELEHILENG	3 Weeks
MOFUTA OA ENCODER	Incremental
TŠEPO	No
E HAHILOE HO SWITCH	No
MOFUTA OA MOFUTHU	Hole for Shaft

Metsu e amanang

SICK DGS35-1L202048	Morekisi oa DGS35-1L202048	Mofani oa DGS35-1L202048
Theko ea DGS35-1L202048	DGS35-1L202048 Litšoantšo	Setšoantšo sa DGS35-1L202048
Datasheet ea PDF ea DGS35-1L202048	DGS35-1L202048 Download Datasheet	Datasheet ea DGS35-1L202048
DGS35-1L202048 Stock	Reka DGS35-1L202048	Reka SICK DGS35-1L202048
SICK DGS35-1L202048	Mofani oa SICK	Morekisi oa SICK
SICK DGS35-1L202048		

Lihlahisoa tse

amanang

 <p>DGS35-1LN00120 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENTAL 120PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>	 <p>DGS35-1KK02048 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2048PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>
 <p>DGS35-1KN02048 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2048PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>	 <p>DGS35-1L402500 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2500PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>
 <p>DGS35-1KK05000 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 5000PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>	 <p>DGS35-1KK01024 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 1024PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>
 <p>DGS35-1K405000 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 5000PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>	 <p>DGS35-1KK02500 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2500PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>
 <p>DGS35-1LN01024 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 1024PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>	 <p>DGS35-1LM01024 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 1024PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>
 <p>DGS35-1L204096 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 4096PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>	 <p>DGS35-1L202500 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2500PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p style="text-align: center;">RFQ</p>