



AVX Corporation

## CP0402A0836ELTR

Karolo ea Karolo:

CP0402A0836ELTR

Moetsi / Mochini:

AVX Corporation

Tlhaloso ea Sehlahisoa

RF DIR COUPLER 824-849MHZ 0402

Datasheets:

 CP0402A0836ELTR.pdf

Boemo ba RoHs

 E na le moetapele / RoHS e sa lumellaneng

Sekepe se Tsoang ho

Hong Kong

Tsela ea Shipment


DHL/Fedex/TNT/UPS/EMS

KOPO EA HO

QOTSA

Setšoantšo e kanna ea ba moemeli. Bona litlhaloso bakeng sa lintlha tsa sehlahisoa.

### Litlhaloso tsa CP0402A0836ELTR

KAROLO EA KAROLO	CP0402A0836ELTR
MOETSI	AVX Corporation
TLHALOSO	RF DIR COUPLER 824-849MHZ 0402
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	E na le moetapele / RoHS e sa lumellaneng
LEQEPHE LA LINTLHA	 CP0402A0836ELTR.pdf
PACKAGE EA LISEBELISOA TSA THEPA	0402
SEHLOOHO	-
KHUTLELA LAHLEHELO	35dB
MATLA - MAX	3W
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0402 (1005 Metric)
MOKHOA OA HO UTLOISISA BOHLOKO (MSL)	1 (Unlimited)
NAKO EA MOETA-PELE E TLOAELEHILENG	10 Weeks
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	Contains lead / RoHS non-compliant
HO ITŠEHLA THAJANA	-51dB
HO LAHLEHELOA KE HO KENYA	0.2dB
HANGATA	824MHz ~ 849MHz
TLHALOSO E QAQILENG	RF Directional Coupler AMPS 824MHz ~ 849MHz 27.2dB 3W 0402 (1005 Metric)
SEPHETHO SA HO KOPANYA	27.2dB
MOFUTA OA LIAPARO	Standard
LIKŌPO	AMPS

### Metsu e amanang

AVX Corporation CP0402A0836ELTR	Morekisi oa CP0402A0836ELTR	Mofani oa CP0402A0836ELTR
Theko ea CP0402A0836ELTR	CP0402A0836ELTR Litšoantšo	Setšoantšo sa CP0402A0836ELTR
Datasheet ea PDF ea CP0402A0836ELTR	CP0402A0836ELTR Download Datasheet	Datasheet ea CP0402A0836ELTR
CP0402A0836ELTR Stock	Reka CP0402A0836ELTR	Reka AVX Corporation CP0402A0836ELTR
AVX Corporation CP0402A0836ELTR	Mofani oa AVX Corporation	Morekisi oa AVX Corporation
AVX Corporation CP0402A0836ELTR	AVX Corporation [MIL] CP0402A0836ELTR	

### Lihlahisoa tse amanang

 <p><b>CP0402A0902ALTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 890-915MHZ 0402 E teng thepeng e teng ka lebenkeleng: 256100 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0402A0836BNTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 269143 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0402A0881ANTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 869-894MHZ 0402 E teng thepeng e teng ka lebenkeleng: 268043 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0402A0881ALTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 869-894MHZ 0402 E teng thepeng e teng ka lebenkeleng: 311288 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0402A0836ANTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 312515 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0402A0836ENTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 266104 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0402A0836CLTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 280051 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0402A0836CNTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 263241 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0402A0942BLTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 925-960MHZ 0402 E teng thepeng e teng ka lebenkeleng: 298807 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0402A0836ALTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 307638 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0402A0836BLTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 824-849MHZ 0402 E teng thepeng e teng ka lebenkeleng: 297451 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0402A0942ALTR</b> Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 925-960MHZ 0402 E teng thepeng e teng ka lebenkeleng: 279032 pcs</p> <p><a href="#">RFQ</a></p>

