



SICK



DGS35-3HK04096

Karolo ea Karolo:

DGS35-3HK04096

Moetsi / Mochini:

SICK

Tlhaloso ea Sehlahisoa

ROTARY ENCODR INCREMENT 4096PPR

Datasheets:

Sekepe se Tsoang ho

Hong Kong

Tsela ea Shipment

DHL/Fedex/TNT/UPS/EMS

KOPO EA HO

QOTSA

Setšoantšo e kanna ea ba moemeli. Bona litlhaloso bakeng sa lintlha tsa sehlahisoa.













Litlhaloso tsa DGS35-3HK04096

KAROLO EA KAROLO	DGS35-3HK04096
MOETSI	SICK
TLHALOSO	ROTARY ENCODR INCREMENT 4096PPR
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	
LEQEPHE LA LINTLHA	
TŠEBELISO EA VOLTAGE	8 V ~ 24 V
TSELA EA HO KHAOTSA	Cable
SEHLOOHO	-
BOPHELO BA ROTATIONAL (LI-CYCLES MIN)	-
PULSES KA REVOLUTION	4096
TLHAHISO EA MOFUTA	-
MABITSO A MANG	1070067
BOEMO BA BOIKUTLO	User Selectable
MOFUTA OA HO THABA	Chassis Mount
NAKO EA MOETA-PELE E TLOAELEHILENG	3 Weeks
MOFUTA OA ENCODER	Incremental
TŠEPO	No
E HAHILOE HO SWITCH	No
MOFUTA OA MOFUTHU	Hole for Shaft

Metsu e amanang

SICK DGS35-3HK04096	Morekisi oa DGS35-3HK04096	Mofani oa DGS35-3HK04096
Theko ea DGS35-3HK04096	DGS35-3HK04096 Litšoantšo	Setšoantšo sa DGS35-3HK04096
Datasheet ea PDF ea DGS35-3HK04096	DGS35-3HK04096 Download Datasheet	Datasheet ea DGS35-3HK04096
DGS35-3HK04096 Stock	Reka DGS35-3HK04096	Reka SICK DGS35-3HK04096
SICK DGS35-3HK04096	Mofani oa SICK	Morekisi oa SICK
SICK DGS35-3HK04096		

Lihlahisoa tse amanang

 <p>DGS35-3HL02048 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2048PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>DGS35-3HK02500 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2500PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>DGS35-3HN00360 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENTAL 360PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>DGS35-3H204096 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 4096PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>DGS35-2LK02048 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2048PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>DGS35-3HK02048 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2048PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>DGS35-3K402048 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 2048PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>DGS35-3K401024 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 1024PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>DGS35-3J408192 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 8192PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>DGS35-2L404096 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 4096PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>DGS35-3KK01024 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 1024PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>DGS35-2LK16384 Bahlahisi: SICK Tlhaloso: ROTARY ENCODR INCREMENT 16384PPR E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>