



AVX Corporation

CP0603B1880AWTR

Karolo ea Karolo:

CP0603B1880AWTR

Moetsi / Mochini:

AVX Corporation

Tlhaloso ea Sehlahisoa

RF DIR COUPLER 1.85-1.91GHZ 0603

Datasheets:

 CP0603B1880AWTR.pdf

Boemo ba RoHs

 E na le moetapele / RoHS e sa lumellaneng

Sekepe se Tsoang ho

Hong Kong

Tsela ea Shipment


DHL/Fedex/TNT/UPS/EMS

KOPO EA HO

QOTSA

Setšoantšo e kanna ea ba moemeli. Bona litlhaloso bakeng sa lintlha tsa sehlahisoa.













Litlhaloso tsa CP0603B1880AWTR

KAROLO EA KAROLO	CP0603B1880AWTR
MOETSI	AVX Corporation
TLHALOSO	RF DIR COUPLER 1.85-1.91GHZ 0603
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	E na le moetapele / RoHS e sa lumellaneng
LEQEPHE LA LINTLHA	 CP0603B1880AWTR.pdf
PACKAGE EA LISEBELISOA TSA THEPA	0603
SEHLOOHO	-
KHUTLELA LAHLEHELO	-33dB
MATLA - MAX	3W
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric)
MOKHOA OA HO UTLOISISA BOHLOKO (MSL)	1 (Unlimited)
NAKO EA MOETA-PELE E TLOAELEHILENG	10 Weeks
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	Contains lead / RoHS non-compliant
HO ITŠEHLA THAJANA	-29dB
HO LAHLEHELOA KE HO KENYA	0.3dB
HANGATA	1.85GHz ~ 1.91GHz
TLHALOSO E QAQILENG	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 17.5 ± 1dB 3W 0603 (1608 Metric)
SEPHETHO SA HO KOPANYA	17.5 ± 1dB
MOFUTA OA LIAPARO	Standard
LIKŌPO	PCS

Metsu e amanang

AVX Corporation CP0603B1880AWTR	Morekisi oa CP0603B1880AWTR	Mofani oa CP0603B1880AWTR
Theko ea CP0603B1880AWTR	CP0603B1880AWTR Litšoantšo	Setšoantšo sa CP0603B1880AWTR
Datasheet ea PDF ea CP0603B1880AWTR	CP0603B1880AWTR Download Datasheet	Datasheet ea CP0603B1880AWTR
CP0603B1880AWTR Stock	Reka CP0603B1880AWTR	Reka AVX Corporation CP0603B1880AWTR
AVX Corporation CP0603B1880AWTR	Mofani oa AVX Corporation	Morekisi oa AVX Corporation
AVX Corporation CP0603B1880AWTR	AVX Corporation [MIL] CP0603B1880AWTR	

Lihlahisoa tse amanang

 <p>CP0603B1880BWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.85-1.91GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>CP0603B1441CWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPL 1.429-1.453GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>CP0603B1950BWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.95GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>CP0603B1842BWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLR 1.805-1.88GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>CP0603B1960AWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.93-1.99GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>CP0603B1620AWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.62GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>CP0603B1960BWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.93-1.99GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>CP0603B0947CWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 935-960MHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>CP0603B1747CWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLR 1.71-1.785GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>CP0603B1842CWTR Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLR 1.805-1.88GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>
 <p>CP0603B1950AW Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.95GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>CP0603B1950CW Bahlahisi: AVX Corporation Tlhaloso: RF DIR COUPLER 1.95GHZ 0603 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>