



ADI (Analog Devices, Inc.)

AD9547BCPZ

Karolo ea Karolo:

Moetsi / Mochini:

Tlhaloso ea Sehlahisoa

Datasheets:

Boemo ba RoHS

Sekepe se Tsoang ho

Tsela ea Shipment

AD9547BCPZ

ADI (Analog Devices, Inc.)

IC CLOCK GEN/SYNCHRONIZR 64LFCSP

 AD9547BCPZ.pdf

 Tataiso ea mahala / RoHS e lumellanang

Hong Kong


DHL/Fedex/TNT/UPS/EMS

KOPO EA HO

QOTSA

Setšoantšo e kanna ea ba moemeli. Bona litlhaloso bakeng sa lintlha tsa sehlahisoa.













Litlhaloso tsa AD9547BCPZ

KAROLO EA KAROLO	AD9547BCPZ
MOETSI	ADI (Analog Devices, Inc.)
TLHALOSO	IC CLOCK GEN/SYNCHRONIZR 64LFCSP
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	Tataiso ea mahala / RoHS e lumellanang
LEQEPHE LA LINTLHA	 AD9547BCPZ.pdf
TŠEBELISO EA VOLTAGE	1.71 V ~ 3.465 V
PACKAGE EA LISEBELISOA TSA THEPA	64-LFCSP-VQ (9x9)
SEHLOOHO	-
BOEMO - BOITSEBISO: PHATLALATSO	2:2
PACKAGING	Tray
PACKAGE / CASE	64-VFQFN Exposed Pad, CSP
PLL	Yes
PHATLALATSO	CMOS, LVDS, LVPECL
MOCHESO O SEBETSANG	-40°C ~ 85°C
PALO EA MAETO	1
MOFUTA OA HO THABA	Surface Mount
MOKHOA OA HO UTLOISISA BOHLOKO (MSL)	3 (168 Hours)
NAKO EA MOETA-PELE E TLOAELEHILENG	26 Weeks
SEPHHO SE SEHOLO	Ethernet, SONET/SDH, Stratum
TEMO EA MAHALA EA BOEMO BO PHAHAMENG / BOEMO BA ROHS	Lead free / RoHS Compliant
HO KENYA	CMOS, LVDS, LVPECL
HANGATA - MAX	725MHz
PHAPANG - HO KENYA: PUO	Yes/Yes
BASE PART NUMBER	AD9547

Metsu e amanang

ADI (Analog Devices, Inc.) AD9547BCPZ	Morekisi oa AD9547BCPZ	Mofani oa AD9547BCPZ
Theko ea AD9547BCPZ	AD9547BCPZ Litšoantšo	Setšoantšo sa AD9547BCPZ
Datasheet ea PDF ea AD9547BCPZ	AD9547BCPZ Download Datasheet	Datasheet ea AD9547BCPZ
AD9547BCPZ Stock	Reka AD9547BCPZ	Reka ADI (Analog Devices, Inc.) AD9547BCPZ
ADI (Analog Devices, Inc.) AD9547BCPZ	Mofani oa ADI (Analog Devices, Inc.)	Morekisi oa ADI (Analog Devices, Inc.)
ADI (Analog Devices, Inc.) AD9547BCPZ	AD AD9547BCPZ	ADI (Analog Devices, Inc.) AD9547BCPZ
Analog Devices Inc. AD9547BCPZ	Analog Devices, Inc. AD9547BCPZ	

Lihlahisoa tse amanang

 <p>AD9544BCPZ-REEL7 Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: BBU DERIVATIVE FOR AD9545 E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>AD9545BCPZ-REEL7 Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: JITTER CLEANER +/PPS + SMALL CEL E teng thepeng e teng ka lebenkeleng: 648 pcs</p> <p>RFQ</p>
 <p>AD9548BCPZ-REEL7 Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: IC CLOCK GEN/SYNCHRONIZR 88LFCSP E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>	 <p>AD9548/PCBZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: BOARD EVAL FOR AD9548 E teng thepeng e teng ka lebenkeleng: 5 pcs</p> <p>RFQ</p>
 <p>AD9545/PCBZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: EVAL BRD FOR JITTER CLEANER +/PP E teng thepeng e teng ka lebenkeleng: 6 pcs</p> <p>RFQ</p>	 <p>AD9547/PCBZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: BOARD EVALUATION FOR AD9547 E teng thepeng e teng ka lebenkeleng: 3 pcs</p> <p>RFQ</p>
 <p>AD9544BCPZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: BBU DERIVATIVE FOR AD9545 E teng thepeng e teng ka lebenkeleng: 13 pcs</p> <p>RFQ</p>	 <p>AD9549A/PCBZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: BOARD EVALUATION FOR AD9549A E teng thepeng e teng ka lebenkeleng: 1 pcs</p> <p>RFQ</p>
 <p>AD9548BCPZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: IC CLOCK GEN/SYNCHRONIZR 88LFCSP E teng thepeng e teng ka lebenkeleng: 8 pcs</p> <p>RFQ</p>	 <p>AD9549ABCPZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: IC CLOCK GEN/SYNCHRONIZR 64LFCSP E teng thepeng e teng ka lebenkeleng: 35 pcs</p> <p>RFQ</p>
 <p>AD9545BCPZ Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: JITTER CLEANER +/PPS + SMALL CEL E teng thepeng e teng ka lebenkeleng: 28 pcs</p> <p>RFQ</p>	 <p>AD9547BCPZ-REEL7 Bahlahisi: ADI (Analog Devices, Inc.) Tlhaloso: IC CLOCK GEN/SYNCHRONIZR 64LFCSP E teng thepeng e teng ka lebenkeleng: Out stock</p> <p>RFQ</p>